

CNC PROFILE SETUP

ADI TOOLS WITH ZOLLER MEASUREMENT

GranQuartz Canada


FRANCK

Cell : 1 819 437-5904

Email : fprunier@granquartz.ca

IMPORTANT

- Create a program with the dimensions in the picture beside.
- Stop each tool of the sequence at 50mm (2in) from each other.
- Visually check that the height (on the Z axis) is good by launching the program using the **LAST** metal position and stopping right before touching the stone.
- Use the same difference of value on every tool of the sequence.
(ex.: MFP5 was 135mm long and the correct position in Z in 140mm; 5mm would be the offset to apply to all the positions)



EXIT
Straight 90° exit

It is **essential** to use black or dark engineered stone


START
Use a straight line for the tool initial path

MICROMETER

- Tool required to have pin point accuracy
- Used to set up CNC tools
- Save time and money
- Made in Japan



Stock No.	Description
128102	0-25 mm
128106	0-1 inch



CNC PROFILE SETUP

ADI TOOLS WITH ZOLLER MEASUREMENT



1


a.



When you receive your EZ Box:

- Check if everything is good
- Keep the box in a dry place
- Carefully read the documents provided and keep them.

b.



Prepare your test piece:

- It is essential to use a black or dark quartz to clearly distinguish the different tool passes.
- The stone thickness has to be very close to 20, 30 or 40 mm to be able to perfectly center the tools.

2




Measure protocol			
Machine	Model	1 / 1	GranQuartz
User	Instal	9/30/2019	3:27:19PM
ID no.	MICR T30-10 8274880		
Date	NOUVEAU		
Remark			
Tool			
Radius	Identifi	Act. value	Tolerance
RADIUS POS4	R274880	0.1477	XZ = 0.03544
LENGTH POS4		0.4462	XZ = 0.03544
RADIUS POS3	N/A	0.3688	XZ = 0.03544
LENGTH POS3	N/A	0.4288	XZ = 0.03544
RADIUS POS2	N/A	0.3181	XZ = 0.03544
LENGTH POS2	N/A	0.4288	XZ = 0.03544
RADIUS POS1	N/A	0.3026	XZ = 0.03544
LENGTH POS1	N/A	0.4288	XZ = 0.03544
RADIUS EXPRESS7	9315151	0.3851	XZ = 0.03544
LENGTH EXPRESS7		0.4059	XZ = 0.03544

Enter the Zoller data:

- It is sometimes necessary to multiply the data (radius) by two to obtain the diameter. Some machines work with Diameters and some work with Radius.

3

a.



Start the program:



- Always start with the last metal position
- Stop right before touching the stone to control the offset on the Z axis

b.



Write down the current dimensions you have (axes x, y, z) or press the button to put everything at 0

c.



Adjusting the dimensions:

- Check if the tool is properly positioned with the stone
- If not, move it manually and very slowly to the desired position
- When the tool is in place look at the new value on the Z axis and calculate how much is your offset
- Then adjust the length of all the other tools in the sequence (same offset)
- * Most of the time your offset will be the same everytime so keep this offset value preciously




4
a.



- b.



- C.



5
a.



b.

[illegible]

**The adjustment on diameter for the last metal shouldn't be much - if you need to adjust a big amount (lets say 0.5mm) something is off in the setup and you might end up with smaller pieces than intended.*






CNC PROFILE SETUP

ADI TOOLS WITH ZOLLER MEASUREMENT



(SUITE)

6



Setting up the polishing wheels:

- Never start adjusting the polishers until the metal positions are perfectly adjusted.
- Stop the first polishing wheel right before it touches the piece
- Write down or reset the current value on all the axes (X,Y and Z)
- Check if the tool is properly aligned with the stone and adjust the height on Z axis if required
- Move forward cautiously in a straight line beside the stone and stop to check the distance or feel the pressure by turning the tool manually.
- Move the polisher forward and/or backwards incrementally to have the perfect pressure or distance with the stone. Calculate the difference between the new position and the start position and apply it to the radius or diameter in the tooling program.
- Restart the program with the dimension modifications you made and stop just before the polisher touches the stone to be sure that everything looks perfect.
- Once the automatic positioning is perfect, restart the program with a 50% feed and increase to 100% if everything is OK.
- If the quality of the polish is less than perfect, you can slightly increase the pressure by decreasing the radius by 0.025mm
- Repeat the previous steps to regulate the second polisher.
- If the shine doesn't seem that good but the pressure seems ok, run a full table with those parameters (light coloured so the job is still be good) - when the job is done, increase the pressure on the polisher by removing 0.025mm on the radius of the tool (0.05mm on the diameter) - This process will break in the polisher without damaging them.



ATTENTION

- * When setting up Express Microlines:
No contact - you shouldn't feel any resistance when manually rotating the tool and you will be able to see a little bit of light between the stone and the polishing wheel (see the picture above) - the rubber tool expands due to centrifugal force
- * When setting up Express Fastlines/ Toplines : Slight contact - you should feel very little resistance when manually rotating the tool but no light should be visible between the tool and the stone
- * **TOO MUCH PRESSURE CAN DESTROY THE TOOL**, that's why we recommend moving .025mm at a time
- * A good way to know if the pressure is good: look at the AMPs before the tool touches the stone and then look at it again when there's contact - the pressure applied should increase the current AMPs on the machine by only 0,1 or 0,2 to a maximum of 0,5 AMP or %.



ANNEX 1

PARAMETERS

DRAWING	TOOL DESCRIPTION	STOCK #	STOCK AVAILABLE (MACHINE) MM	STOCK AVAILABLE (MACHINE) INCHES	STOCK REMOVAL (MICROMETER) MM	STOCK REMOVAL (MICROMETER) INCHES	STANDARD RPM	STANDARD FEED RATE MM/MIN	STANDARD FEED RATE IN/MIN
	EURO SEEM POS 1 D=60MM, H=35MM	PB01013	0,65	0,0256	0,3 OR SHAPE	0,12 OR SHAPE	6000	1500	59
	EURO SEEM VACUUM POS 1 D=60MM, H=35MM	PB40629	0,65	0,0256	0,3 OR SHAPE	0,12 OR SHAPE	6000	1500	59
	FAST LINE T30-10 POS 1	PB124166	0,35	0,0138	0,3	0,0118	5500	1500	59
	FAST LINE T30-10 POS 2	PB124167	0,15	0,0059	0,2	0,0079	5500	4000	157
	FAST LINE T30-10 POS 3	PB124168	0,05	0,0020	0,1	0,0039	5500	3000	118
	FAST LINE T30-10 POS 4	PB124169	0	0,0000	0,05	0,0020	5000	1200	47
	FAST LINE T30-10 MFP5	PB01634	0	0,0000	0,05	0,0020	4500	1000	39
	FAST LINE T30-10 MAGIC 5	PB691148	COMP:0,01	COMP:0,00024	COMP:0,01	COMP:0,00024	2500	1000	39
	FAST LINE T30-10 MAGIC 6	PB691149	COMP:0,01	COMP:0,00024	COMP:0,01	COMP:0,00024	2500	1000	39
	FAST LINE T30-10 EXPRESS 6	PB021347	0	0,0000	0	0,0000	3000	1000	39
	FAST LINE T30-10 EXPRESS 7	PB021348	0	0,0000	0	0,0000	3000	1000	39
	Z WHEEL MICRO POS 1 D=20MM	PB20769	0,65	0,0256	0,3 OR SHAPE	0,12 OR SHAPE	6500	800	31
	ELECTROPLATED FINGER BIT D16X35MM	PB25008	0,65	0,0256	0,3 OR SHAPE	0,12 OR SHAPE	6500	800	31
	MICRON LINE T30-10 POS 1	PB20826	0,35	0,0138	0,3	0,0118	6500	1000	39
	MICRON LINE T30-10 POS 2	PB20827	0,15	0,0059	0,2	0,0079	6500	1000	39
	MICRON LINE T30-10 POS 3	PB20828	0,05	0,0020	0,1	0,0039	6500	1000	39
	MICRON LINE T30-10 POS 4	PB20829	0	0,0000	0,05	0,0020	6000	800	31
	MICRON LINE T30-10 MFP5	PB015040	0	0,0000	0,05	0,0020	4500	800	31
	MICRON LINE T30-10 MAGIC 5	PB67067	COMP:0,01	COMP:0,00024	COMP:0,01	COMP:0,00024	3000	800	31
	MICRON LINE T30-10 MAGIC 6	PB67068	COMP:0,01	COMP:0,00024	COMP:0,01	COMP:0,00024	3000	800	31
	MICRON LINE T30-10 EXPRESS 6	PB021143	0	0,0000	0	0,0000	3500	1000	39
	MICRON LINE T30-10 EXPRESS 7	PB021144	0	0,0000	0	0,0000	3500	1000	39